



P.O. Box 1206 • Pryor, OK 74361
 Phone (918) 825-7222 • Fax (918) 825-0723
 www.rae-corp.com

PSYCHROMETRIC CHART

Normal Temperature
 I-P Units

SEA LEVEL

BAROMETRIC PRESSURE: 29.921 in. HG




Chart by: HANDS DOWN SOFTWARE, www.handsdownsoftware.com





P.O. Box 1206 • Pryor, OK 74361
 Phone (918) 825-7222 • Fax (918) 825-0723
 www.rae-corp.com

PSYCHROMETRIC CHART

Normal Temperature
 SI Units

SEA LEVEL

BAROMETRIC PRESSURE: 101.325 kPa




Chart by: HANDS DOWN SOFTWARE, www.handsdownsoftware.com

